



## REPORTE DE INCIDENTE

### Datos Generales de Viaje

Fecha de Salida	20/2/2024	W/O	
Fecha de incidente		Cliente	Hapag Lloyd
Fecha de Ingreso	29/2/2024	Nº Contenedor	
Nº EIR	170538	Ruta	

### Datos Generales del Transporte

### Datos Generales del Equipo

Empresa	Transporte Sinai	Prefijo	
Nombre	Roberto Cabrera	Numero	531728
Licencia		Nº Gent Set	N/A
Marca/Color de Cabezal	Kemwork/Negro	Placa	TRA0064
Placa	TCI4658	Color	Negro

### Datos Generales de Incidente

Llanta Nº	Tamaño	Marca	Diseño	Orig./Reenc.	Lonas	Dot	MM	Pos.	Causa del Retiro
EXA2204340	11R22.5	KUN LUN	kt865	Original	16	4621	9	1	Estallada (Golpe En Costado)



#### Comentarios:

Llanta posicion 1 estallada por costado , llanta presenta golpe en costado falla operativa

#### Nota:

Llanta original 11R22.5

W/O = Work Order N/D = No Disponible N/A = No Aplica Orig./Reenc. = Original o Reencauche MM = Milimetros Pos. = Posicion

Roberto Cabrera  
Entrego

Erik Moreno  
Recibio

Lorenzo Varela  
Supervisor



## Gate In Interchange



EXA S.A.

TIR# 170538

170538

PUERTO CORTES

Account: CHASIS EXA PUERTO CORTES

Container:	Size & Type: 4045CH	Date In: 2/29/2024 9:11:00 AM			
Chassis: 531728	Size Chassis: 4045CH	FMCSA:			
Genset:	Size Genset:	Control #:			
Gen Fuel:	Vent Setting:	Reef Temp:			
Reef Hour:	Reef Serial:	Gen Hour:			
Booking:	BL #:	Loaded: E			
Shipper:	Voyage #:	Seal #:			
Vessel: SPS	Lot Location:				
Container Condition		Chassis Condition			
		AV			
Unit Type	Damage/Loc	Description	Damages	Damage/Loc	Description

Container  
Chassis

Container Lease Information				Remarks: LLANTA 1 ESTALLADA
Off Lease From:	DPP 0.00			
Delivery #	Lease:			
LFO LFI	Outside 2204340	Inside 2204341	RFO RFI	Outside 2204343
LMO LMI			RMO RMI	Inside 2204342
LRO LRI	Outside 2204344	Inside 2204345	RRO RRI	Outside 2204347
				2204346

X

Erik Moreno

X

RC

Inspected By: OPERACIONE

Carrier: TRANSPORTE PAZ

ROBERTO CABRERA  
Truck# TCI4658  
TRPA  
2/29/2024 9:11:00 AM  
Licencia: