



REPORTE DE INCIDENTE

Datos Generales de Viaje

Fecha de Salida	13/8/2025	W/O	
Fecha de incidente		Cliente	Cervecería Hondureña
Fecha de Ingreso	15/8/2025	Nº Contenedor	MSMU6321766
Nº EIR	227790	Ruta	Pto Cortes/Saba/Pto Cortes

Datos Generales del Transporte

Empresa	Tranexapa Particulares	Prefijo	
Nombre	Olivio Flores	Numero	460722
Licencia	0801-1986-11721	Nº Gent Set	S/N
Marca/Color de Cabezal	FL/Blanco	Placa	TRA9941
Placa	TCJ5624	Color	Rojo

Datos Generales de Incidente

Llanta N°	Tamaño	Marca	Diseño	Orig./Reenc.	Lonas	Dot	MM	Pos.	Causa del Retiro



Comentarios:

Llanta posición 1,2 y 7 no es de EXA

Nota:

Chasis andaba con llanta 11R22.5 Reencauchadas

W/O = Work Order N/D = No Disponible N/A = No Aplica Orig./Reenc. = Original o Reencauche MM = Milímetros Pos. = Posicion

Olvin Flores
Entrego

Roberto Cantarero
Recibio

Lorenzo Varela
Supervisor



Gate In Interchange



EXA S.A.

TIR# 227790

227790

PUERTO CORTES

Account: CHASIS EXA PUERTO CORTES

Container:	Size & Type:	4045CH	Date In:	8/15/2025 10:09:00 AM	
Chassis: 460722	Size Chassis:	4045CH	FMCSA:		
Genset:	Size Genset:		Control #:		
Gen Fuel:	Vent Setting:		Reef Temp:		
Reef Hour:	Reef Serial:		Gen Hour:		
Booking:	BL #:		Loaded:	E	
Shipper:	Voyage #:		Seal #:		
Vessel: LA CEIBA	Lot Location:				
Container Condition			Chassis Condition		
		AV	AV		
Unit Type	Damage/Loc	Description	Damages	Damage/Loc	Description

Container
Chassis

Container Lease Information		Remarks:	
Off Lease From:	DPP 0.00	TRAELLLANTA 1-2 Y 7 NO PERTENECEN A EXA	
Delivery #	Lease:		
LFO LFI	Outside	Inside	Outside
LMO LMI			RFO RFI
LRO LRI			RMO RMI
			RRQ RRI

X

X

Inspected By: EIR3

Carrier: EXA VARIOS

OLVIN FLORES
Truck# TCJ5624
EXAVRI
8/15/2025 10:09:00 AM
Licencia: