



REPORTE DE INCIDENTE

Datos Generales de Viaje

Fecha de Salida	13/8/2025	W/O	
Fecha de incidente		Cliente	Cervecería Hondureña
Fecha de Ingreso	15/8/2025	Nº Contenedor	MSMU6321766
Nº EIR	227783	Ruta	Pto Cortes/Saba/Pto Cortes

Datos Generales del Transporte

Empresa	Tranexapa Particulares	Prefijo	
Nombre	Mario Martinez	Numero	691135
Licencia	0319-1980-00400	Nº Gent Set	S/N
Marca/Color de Cabezal	FL/Rojo	Placa	TRC4147
Placa	HBB5270	Color	Anaranjado

Datos Generales de Incidente

Llanta Nº	Tamaño	Marca	Diseño	Orig./Reenc.	Lonas	Dot	MM	Pos.	Causa del Retiro



Comentarios:

Llanta posición 3 no es de EXA

Nota:

Chasis andaba con llanta 11R22.5 Reencauchadas

W/O = Work Order N/D = No Disponible N/A = No Aplica Orig./Reenc. = Original o Reencauche MM = Milímetros Pos. = Posicion

Mario Martinez
Entrego

Roberto Cantarero
Recibio

Lorenzo Varela
Supervisor



Gate In Interchange

EXA S.A.

TIR# 227783



227783

PUERTO CORTES

Account: CHASIS EXA PUERTO CORTES

Container:	Size & Type:	45CH	Date In:	8/15/2025 9:48:00 AM
Chassis: 691135	Size Chassis:	45CH	FMCSA:	
Genset:	Size Genset:		Control #:	
Gen Fuel:	Vent Setting:		Reef Temp:	
Reef Hour:	Reef Serial:		Gen Hour:	
Booking:	BL #:		Loaded:	E
Shipper:	Voyage #:		Seal #:	
Vessel: SABA	Lot Location:			
Container Condition			Chassis Condition	
		AV	AV	
Unit Type	Damage/Loc	Description	Damages	Damage/Loc
Container				
Chassis				

Container Lease Information				Remarks:	
Off Lease From:			DPP 0.00	LLANTA POSICION 3 NO PERTENECE A EXA	
Delivery #			Lease:		
LFO LFI	Outside 1909139	Inside 2201188		Outside RFO RFI 1801871	Inside 2204380
LMO LMI				RMO RMI	
LRO LRI	Outside 1710519	Inside 2205496		RRO RRI 2203186	Inside 2203500

X

X

Inspected By: EIR3

Carrier: EXA TXPA PART

MARIO MARTINEZ

Truck# HBB5270

EXATPA

8/15/2025 9:48:00 AM

Licencia: TRC4147