




Gate In Interchange



EXA S.A.

TIR# 116844

116844

PUERTO CORTES

Account: CHASIS EXA SAN LORENZO

Container:	Size & Type: 40CH3A	Date In: 24/4/2022 19:57:00
Chassis: 446077	Size Chassis: 40CH3A	FMCSA:
Genset: A81799	Size Genset: 00GU	Control #:
Gen Fuel: 0 Gal	Vent Setting:	Reef Temp:
Reef Hour:	Reef Serial:	Gen Hour: 7511.9
Booking: ACAJUTLA MSK 250422	BL #:	Loaded: E
Shipper:	Voyage #:	Seal #:
Vessel:	Lot Location:	
Container Condition		Chassis Condition
AV		AV

<u>Unit Type</u>	<u>Damage/Loc</u>	<u>Description</u>	<u>Damages</u>	<u>Damage/Loc</u>	<u>Description</u>
------------------	-------------------	--------------------	----------------	-------------------	--------------------


Container

Chassis

Container Lease Information				Remarks:	
Off Lease From:		DPP 0.00			
Delivery #		Lease:			

	Outside	Inside		Outside	Inside
LFO LFI	2104861	2104862	RFO RFI	1902530	1102177
LMO LMI	1811964	1508697	RMO RMI	2202130	1611485
LRO LRI	2202131	2202132	RRO RRI	2202134	2202133

X



Inspected By: EIRSLO

X

OSWALDO

Carrier: EXA TXPA PART

OSWALDO ANTUNEZ

Truck# AAR5905

EXATPA

24/4/2022 19:57:00

Licencia: