




Gate In Interchange



EXA S.A.

TIR# 116842

116842

PUERTO CORTES

Account: CHASIS EXA SAN LORENZO

Container:	Size & Type: 40CH3A	Date In: 24/4/2022 19:35:00
Chassis: 216605	Size Chassis: 40CH3A	FMCSA:
Genset: D99509	Size Genset: 00GU	Control #:
Gen Fuel: 4 GLS	Vent Setting:	Reef Temp:
Reef Hour:	Reef Serial:	Gen Hour: 0334.3
Booking: ACAJUTLA MSK 250422	BL #:	Loaded: E
Shipper:	Voyage #:	Seal #:
Vessel:	Lot Location:	
Container Condition		Chassis Condition
AV		AV

Unit Type	Damage/Loc	Description	Damages	Damage/Loc	Description
-----------	------------	-------------	---------	------------	-------------

Container
Chassis

Container Lease Information				Remarks:	
Off Lease From:		DPP 0.00		EQUIPO INGRESO CON 1 PULGADA DE DIESEL	
Delivery #		Lease:			

	Outside	Inside		Outside	Inside
LFO LFI	2101307	2101308	RFO RFI	21013010	2101309
LMO LMI			RMO RMI		
LRO LRI	2203210	2203211	RRO RRI	2203213	2203212

X



Inspected By: EIRSLO

X

Jose V

Carrier: EXA SAN LORENZO CARRIER

JOSE VELASQUEZ
JOSE VELASQUEZ
Truck# AAM9756
ESLCAR
24/4/2022 19:35:00
Licencia: