




# Gate Out Interchange



EXA S.A.

TIR# 116507

116507

PUERTO CORTES

Account: CHASIS EXA SAN LORENZO

|                            |                      |                              |
|----------------------------|----------------------|------------------------------|
| Container:                 | Size & Type: 40CH3A  | Date Out: 20/4/2022 08:54:00 |
| Chassis: <b>446077</b>     | Size Chassis: 40CH3A | FMCSA:                       |
| Genset: <b>A81799</b>      | Size Genset: 00GU    | Control #:                   |
| Gen Fuel: 50 GLS           | Vent Settings:       | Reef Temp:                   |
| Reefer Hours:              | Reefer Serial:       | Gen Hour: 7484.7             |
| Booking: CORINTO20/04/2022 | BL #                 | Loaded: E                    |
| Shipper:                   |                      | Seal #                       |
| Vessel:                    | Voyage #             |                              |

## Container Condition

|  |
|--|
|  |
|--|

## Chassis Condition

|    |    |
|----|----|
| AV | AV |
|----|----|

|                             |     |      |
|-----------------------------|-----|------|
| Container Lease Information |     |      |
| Off Lease From:             | DPP | 0.00 |
| Pickup #                    |     |      |

|          |
|----------|
| Remarks: |
|----------|

|         | Outside | Inside  |         | Outside | Inside  |
|---------|---------|---------|---------|---------|---------|
| LFO LFI | 2104861 | 2104862 | RFO RFI | 1902530 | 1102177 |
| LMO LMI | 1811964 | 1508697 | RMO RMI | 2202130 | 1611485 |
| LRO LRI | 2202131 | 2202132 | RRO RRI | 2202134 | 2202133 |

X \_\_\_\_\_

Inspected By: EIRSLO

X 

Carrier: EXA TXPA PART

OSWALDO ANTUNEZ

Truck# AAR5905

EXATPA

20/4/2022 08:54:00

licencia: