



**Messrs.:** EXA

**Attn'n:** Ms. HONORIA RODRIGUEZ

**Client:** EXA

**Client Reference:** N/A

**Our Reference:** OTIHN22-0585

**Facilities:** YONKER RECONCO

**Location:** SIGUATEPEQUE, COMAYAGUA

**Inspection Date:** AUGUST 27<sup>th</sup>, 2022

Attached for your review please find our original inspection report covering the above detailed shipment. Should you have any questions regarding this report, please do not hesitate to contact us.

Thank you for providing Oil Test Internacional with the opportunity to be of service to you.

It is my sincere hope that you are completely satisfied with the service which was provided to you and will avail yourself of our expertise again in the future.

We are always interested in suggestions that would allow us to improve upon our already high standards and encourage you to submit your thoughts. Again, thank you.

Respectfully  
**AGRI & DRY CARGO DIVISION**

A handwritten signature in black ink, appearing to read 'Roger Munguia'.

original signature on file

ROGER MUNGUIA

**OIL TEST INTERNACIONAL**



**CORRESPONDING TO:** CARGO INSPECTION

**CUSTOMER:** EXA

**FACILITIES:** YONKER RECONCO

**VOYAGE No.:** N/A

**LOCATION:** SIGUATEPEQUE, COMAYAGUA

**OIL TEST INTERNATIONAL REF:** OTIHN22-0585

**YOU'RE REFERENCE:** N/A

**INSPECTION COMMENCED:** AUGUST 27<sup>th</sup>, 2022

**INSPECTION COMPLETED:** AUGUST 27<sup>th</sup>, 2022

**REPRESENTATIVE:** Ms. HONORIA RODRIGUEZ

**INSPECTOR'S NAME:** D. VENTURA



**CLIENT** : EXA **OTI REF** : OTIHN22-0585  
**DATE** : AUGUST 27<sup>th</sup>, 2022 **YOUR REF** : N/A  
**PRODUCT** : USES AUTO PARTS  
**FACILITIES** : YONKER RECONCO

OTI de Honduras, S.A. of C.V., acting as independent inspectors as requested by Messer EXA, we attended the Physical Inspection of 1x40' container unit, at **YONKER RECONCO** Located in Siguatepeque, Comayagua, Honduras. Obtaining the following results.

**CARGO DETAILS (As per SEA-WAYBILL)**

BILL OF LADING		MEDUU5946576
SHIPPER	CONSIGNEE	NOTIFY PARTY
	JENNY VANESSA TORO HERNANDEZ / YONKER RECONCO, CARRETERA CA5 1 KILOMETRO ANTES DE LA ENTRADA PRINCIPAL DE SIGUTEPEQUE RTN 0501-1981-051395	AGENCIA TREJOS LESVIA CALIX 504-2559-0966 JENNY VANESSA TORO HERNANDEZ 504-3308-2028
VESSEL	PORT OF LOADING	PORT OF DISCHARGE
TUCANA VOY: 2099S	PT EVERGLADES, USA	PUERTO CORTES
SEAL	No. CONTAINER	SIZE CONTAINER
2233051 3101904	KOSU 452059-3	40 FEET

Commodities	Quantity as per Bill of Lading	Damaged	Damaged %
USED AUTO PARTS	185 PC	Not Determined	N/A
TYPE OF DAMAGE: Not Determined			

This report was issued in Siguatepeque, Comayagua, Honduras, on August 27th, 2022, in good faith and without prejudice as to the rights of whom it may concern

For, 7/10

**ROGER MUNGUA  
OPERATION SUPERVISOR**



## DAMAGED INSPECTION

**CLIENT** : EXA  
**DATE** : AUGUST 27<sup>th</sup>, 2022  
**PRODUCT** : USED AUTO PARTS  
**FACILITIES** : YONKER RECONCO

**OTI REF** : OTIHN22-0585  
**YOUR REF** : N/A

On August 27th, 2022, the **OIL TEST INTERNACIONAL** inspector did attend at the facilities of **YONKER RECONCO**, located at **SIGUATEPEQUE, COMAYAGUA, HONDURAS**. to carry out the inspection of 1x40' Container stuffed with **185 Pieces of Used Auto Parts**.

The inspection commenced on **August 27<sup>th</sup>, 2022, from 17:50 until 21:00 hours**, and was carried out jointly with the support of **YONKER RECONCO** personnel.

The inspector arrived at the facilities on August 27 at 17:50, Upon arrival, the inspector found that the seal had already been broken, the container doors had been opened, and the cargo had begun to be discharged.

During the discharging of the cargo, photographs of the process were taken.

It was not possible to determine the quantity and condition of the pieces because the Yonker personnel in charge of discharging, determined that they would only discharge the cargo and the count and damage verification would take place until Monday, August 29, 2022.

This report was issued in San Pedro Sula, Cortes, Honduras, on august 27th, 2022, in good faith and without prejudice as to the rights of whom it may concern

**AGRI & DRY CARGO DIVISION**

A handwritten signature in black ink, appearing to read 'Roger Munguia'.

Roger Munguia  
OTI de Honduras

## PHOTOGRAPHIC REPORT























